

Fig. 1
(Prior Art)




Fig. 2
(Prior Art)




Fig. 3





Fig. 4



500 Fig. 5




Fig. 6




Fig. 7

208020" 2892400T




Fig. 8




Fig. 9

Output Ports
1104

	Output Port 0	Output Port 1	Output Port 2	Output Port 3
Input Port 0	Insertion Loss Value A	Insertion Loss Value B	...	
Input Port 1	Insertion Loss Value C	Insertion Loss Value D	...	
Input Port 2	Insertion Loss Value E	Insertion Loss Value F	...	
Input Port 3	⋮	⋮		

Input
Ports
1102

Fig. 11A

Output Ports
1104

	Output Port 0	Output Port 1	Output Port 2	Output Port 3
Input Port 0	Time Value A	Time Value B	...	
Input Port 1	Time Value C	Time Value D	...	
Input Port 2	Time Value E	Time Value F	...	
Input Port 3	⋮	⋮	⋮	

Input
Ports
1102

Fig. 11B